



Existing Condition:  
The pole leaning against eave and gutter.

Below: Wires crossing Pat's property through a tree that needs to be remove.



Existing Condition:  
The pole is very short and it is urrently leaning and in contact with eaves and gutters.  
The existng tree can not be removed until power lines are relocated.



Existing Condition:  
From one pole located on the street three homes are currently connected. The Gagne's and the O'Donnell's power lines cross 30 Rector Street in order to connect to the existing pole at the corner of Pat's home that is located on the O'Donnell's property.